



Lubrication Positions




Delta 110-C-SSS



Lubrication of spindle drive (**S**).
Lubrication of guiding carriages
1+2 and 3+4 (**F**).

The spindle drive and guiding carriages must
be lubricated through all three funnel grease
nipples on either side.


Delta 145-C-SSS



Lubrication of spindle drive (**S**).
Lubrication of guiding carriages
1+2 and 3+4 (**F**).

The spindle drive and guiding carriages must
be lubricated through all three funnel grease
nipples on either side.


Delta 200-SSS



Lubrication of spindle drive (**S**).
Lubrication of guiding carriages
1 through 4 (**F**).

The spindle drive and guiding carriages must
be lubricated through both funnel grease
nipples on either side.

Delta 240-SSS



Lubrication of spindle drive (**S**).
Lubrication of guiding carriages
1 through 4 (**F**).

The spindle drive and guiding carriages must
be lubricated through both funnel grease
nipples on either side.

Lubrication Points for Delta Linear Units with Spindle Drive

Delta 240-C-SSS



Lubrication of spindle drive (**S**).
Lubrication of guiding carriages
1 through 4 (**F**).

The spindle drive and guiding carriages must
be lubricated through both funnel grease
nipples on either side.